







Operating

XAC 8713 PENDANT CONTROL STATION

Vibration Resistance





TECHNICAL DETAILS	
Operating Temperature	-15°C to +70°C (-5°F to +158°F)
Storage Temperature	-40°C to +70°C (-40°F to +158°F)
Housing Materia	Yellow polypropylene V2
Shock Resistance	100 g

15 g for 40 to 500 Hz